

## BRIEFING PAPER

### Regulatory Status and Involvement in the Orange County Groundwater Protection Project – South Basin

#### Executive Summary

The Orange County Water District (OCDW) has identified two groundwater areas (South and North Basins) within its jurisdiction that are impacted primarily by volatile organic compounds. Two impacted area are about 7 miles apart (see Figure 1).

- Product well impacted: 1 well (IRWD-3) – see Figure 1 for location.
- Sources of releases: 55 sources of releases identified by OCWD. See Tables 1 for the status of these sources of releases. See Figures 2 for the location of the sources.
- DTSC's sites: 9 sites listed in the DTSC's EnviroStor. (5 actively managed)
- OCDW's activities: groundwater grab sampling conducted. No remediation in this basin.

#### OCDW's Recommendations

- OCWD plans to remediate the regional contaminated plumes and recommends that the State regulatory agencies and potentially USEPA address the site specific source area by controlling and/or removing the source from specific sites.

#### Status of DTSC's Actively Managed Sites

- Embee Plating: this is a metal plating facility with a Corrective Action Consent Agreement issued in 2012. Onsite soil, soil vapor and groundwater investigations. Contaminates detected include metals (such as hexavalent chromium, chromium, cadmium, copper, nickel, etc.), volatile organic compounds and perchlorate. Limited enhanced bio-remediation as interim measures is being implemented to control the off-site migration. Indoor air samples were also sampled and indicated that there is no immediate human health concerns. Embee is evaluating the need to expand the interim measures. Groundwater monitoring continues at the site.
- Holchem: This was a chemical distributor and waste recycling and transfer facility. A dual phase extraction system was implemented but discontinued at this time. Groundwater monitoring is being implemented at the site. DTSC issued an Order on April 2, 2014 to continue the cleanup activities under Chapter 6.8.

- Engineering Plating: The facility operations ceased in 2003. An ISE Order was issued in August 2013 to the former owner but no response was received from the owner. DTSC is currently conducting a potential responsible parties search.
- Cherry/Textron: This is a fastening system manufacturer that operates a wastewater treatment system under PBR. A CACA was issued in 2009. Onsite soil, soil gas and groundwater investigation were conducted. VOC was the major contamination identified in the facility. Groundwater monitoring continues at the site. The facility conducted a dual phase extraction pilot study and is in process of proposing a remediation to control the migration of contaminated plume toward off-site. Cherry is also revising its indoor air sampling workplan for DTSC's approval. Cherry expects to propose interim measures under Chapter 6.8 by June 2014.


TABLE 1 - ORANGE COUNTY GROUNDWATER PROTECTION PROJECT -SOUTH BASIN

	Site Name	Approximate Distance And	Agency Status	Current Activity	GW Remediation
1	Gallade Chemical (aka Avalon Chem Co., aka Orange County Chemical Co.)	2,700 - NNE	Active (RWQCB/ DTSC-post closure)	Assessment and remediation	Groundwater pump and treat; dual phase extraction (combination groundwater extraction, soil vapor extraction)
2	Embee Plating	2,600 - NNE	Active (DTSC - C.Yen)	Assessment and pilot study remediation	RCRA CA - enhanced bio
3	Holchem / Service Chem Co. (aka Brenntag West, aka SOCO)	2,400 - NE	Active (USEPA/DTSC - R. Romero))	Assessment and limited remediation and pilot testing	Soil Thermal oxidizer system installed, SVE conducted, and high vacuum extraction test conducted
4	Diceon Electronics (aka Kosakvra Assoc.; aka CA Environmental Engineering; aka George Gemayel)	2,100 - NNE	Active (RWQCB)	Monitoring	None implemented as of 2006
5	GE Plastics (aka LNP Plastics)	4,400 - E	Active (RWQCB)	Assessment and remediation	Interim pump and treat. Insitu biodegradation being pilot tested in 2005
6	Universal Circuits (aka Remedial Counsel Comm.)	5,100 - NE	Active (RWQCB)	Post remediation monitoring	Excavation and dual phase groundwater and vapor extraction system in operation (2007).
7	Colonial Engineering and Mobil 35 Chemical (BASF)	4,200 - W	Active (RWQCB)	Post remediation monitoring	Excavation, Insitu oxidation proposed, Implementation
8	ASTECH (aka Aloca Composites	4,800 - SE	Active (RWQCB)	Post remediation monitoring	Excavation and pump and treat

	Site Name	Approximate Distance And	Agency Status	Current Activity	GW Remediation
9	Circuit One (aka L. H. Research; aka Martin Companies)	3,500 - NE	Active (RWQCB)	Monitoring and remediation	Dual phase groundwater and vapor extraction
10	Troy Computer (aka Revere Financial)	4,700 - E	Active (Agency?)	Monitoring and remediation	Dual phase groundwater and vapor extraction
11	Bell Industries	6,600 - NE	Active (RWQCB)	Monitoring and remediation	Groundwater pump and treat
12	BFM Energy Prod (aka DRSS-1; aka BFM Aerospace, aka Integrated Aerospace Systems; aka Smiths Aerospace)	4,300 - SE	Active (RWQCB)	Monitoring and remediation	Pump and treat and enhanced bioremediation
13	Kugel Trust Prop (aka Interconnection Prod, aka McDonald Packaging)	4,700 - W	Closed (RWQCB)	Closed	Excavation, groundwater and vapor recovery
14	Emerson Electric (aka Emerson Computer Power)	3,700 - S	Closed (RWQCB)	Closed	Dual phase groundwater and vapor extraction; subsurface bentonite containment wall and groundwater extraction; dual phase extraction with air sparging and hydrogen peroxide
15	Extruded Plastics (aka Griffin Electronics; aka Style Craft)	2,200 - NNE	No files (EPA)	None	Excavation near a wastewater sewer line break
16	Orange Coast Plating (Nipon Engine Spec)	3,800 - W	Closed (DTSC)	None	Excavation
17	Commercial Chem (aka Tibbetts Newport Company; aka Gerald F. Mattingly Trustee)	4,000 - WNW	Closed (local agency)	Closed	USTs removed
18	West Coast Coatings (aka Berkeley Invest., aka Silver Wood Landscaping)	4,400 - NE	Active (local agency)	Remediation	UST removed and excavation; additional institu remediation of Cr-VI proposed in 2005
19/2	Tolo Inc. (aka	4,000 - E	Closed	Inactive	UST removed

Site Name	Approximate Distance And	Agency Status	Current Activity	GW Remediation
5 Pullman/Carnegie Industrial Center, aka Pullman Partners) and PDA Engineering				
20 Micromotors Inc. (Pro Dex)	4,100 - SW	Closed (RWQCB)	Inactive	Excavation and backfilling
21/3 Griswold Controls (aka 3 Walco Manufacturing) and City Center Industrial Park	3,000 - WSW	Active (RWQCB)	Monitoring and remediation	Excavation and SVE, currently (2006) in-situ bioremediation
22 Industrial Building (aka SETCO, Inc.)	4,700 - W	Closed (OCHCA)	Inactive	Excavation
23 Engineering Plating (aka A-1 QUARTZ CO (aka Circuit Express, aka Europa Wheels)	4,900 - NNE	Active (DTSC-H. Hashemian)	Investigation	
24 Ingram Micro	5,500 - NE	Closed	Closed	none implemented as of 2006
26 Santa Ana City Yard	1,600 - NW	Inactive (RWQCB)	Inactive	UST removal and excavation
27 Rheem Metals	5,000 - NNE	Inactive (DTSC)	Inactive	???
28 Aluminum Forge (Div. of Altamil Corp.)	2,700 - SSW	Closed	Inactive	???
29 Dyer Business Park (aka former Accurate Circuit)	2,100 - S	Active (RWQCB)	Monitoring and remediation	UST removal, excavation, and pilot testing of dual phase extraction
30 AF Milliron Co / Diesel Logistics (aka Beard Printin	2,200 - NE	Inactive (DTSC-R. Ahmed)	Investigation (PEA)	???
31 Griffin Electronics	2,300 - NE	Inactive	Inactive	Excavation
32 McKesson Chemical (aka Foremost & McKesson; aka Marconi Racing)	9,100 - NE	Inactive		
34 Textron Fastening Systems - Aerospace (aka Cherry Textron)	1,100 - NE	Active (DTSC - C. Yen)	GW monitoring, Remedial action underway	RCRA CA - DPE Extraction pilot study

	Site Name	Approximate Distance And	Agency Status	Current Activity	GW Remediation
35	ITT Cannon	1,200 SE	Active (RWQCB)	Remedial action underway	UST removed, dual phase extraction and treatment, insitu reductive dechlorination
36	Drake Engineering	5,000 - SSE	Active (RWQCB)	Inactive	UST removal and soil excavation
37	PC World	7,600 - SE	Closed (RWQCB)	Inactive	Excavations
39	Arco Welding Manufacturing	2,300 WSW	Closed (RWQCB)	Inactive	None
40	Transmission Master	3,700 - NW	Closed (RWQCB)	Inactive	UST removed
41	Normandy Partners	8,900 - NNE	Closed (RWQCB)	Inactive	???
42	Ricoh Electronics	4,900 - S	Active (RWQCB)	Remediation and monitoring	Excavation and pump and treat
43	Xerox Corporation Facility	10,200 - NE	Closed (DTSC - P. Acharya)	Inactive	Removal of tanks and piping, excavation and SVE
44	US Polymetric	1,300 - SE	Closed (DTSC - P. Acharya)	Inactive	USTs removed and soil excavation
45	Rockford Aerospace Products	5,600 - SE	Inactive	Inactive	???
46	Tustin Marine Corps Air Station	11,000 - ESE	Active (DTSC - A. Peddada)	Remediation and monitoring	various
47	Newport Corporation	6,500 - SE	Closed	Inactive	Soil excavation
48	Break-Free Inc	8,700 - NNE	Closed (DTSC)	Inactive	Excavation
49	Steel Case Inc.	4,500 - ENE	Active	Post remedial action monitoring	Dual phase extraction and treatment
50	USCO Distribution Service, Inc	1,500 - SSW	Closed (RWQCB)	Inactive	UST removal, soil excavation, and pump and
51	TDK Engineering	4,400 - SSE	Closed	Inactive	UST removal and soil excavation
52	Unisys/Memorex	5,600 - SSE	Active (RWQCB)	Post remedial action monitoring	Pump and treat and monitoring of natural attenuation
53	Classique cleaners	9,000 - NE	Closed	Inactive	None
54	Mitchel Rubber Co.	5,100 - SSE	Closed	Inactive	None
55	Edwards Lifesciences	5,400 - SE	? (RWQCB)	Inactive	UST removal and excavation



○ Contaminated plume identified in North Basin

○ Potential sources of releases identified for investigation in South Basin

FIGURE 2 - OTHER SOURCES IN ORANGE COUNTY SOUTH BASIN

